

Super Salvage

No permit

Building since 1992

Employees 26 haul
36 MP site) 66 total

1991 - 2 Owners Bob & Dernie Gordon

1995 - 99% to employees

2003 - Joel

2008 - to employees

~~Photo taken 2/20/13
Scrap yard
Super Salvage~~

- 1 entrance sign, someone leaving site, truck out
- 2 Berm, entrance at site
- 3 tank, lubricants, @entrance, pallet
- 4 lubricants, close up of label
- 5 Overall view of pond from street
- 6 riser in pond.
- 7 Close up view at sheen
- 8 close up of sheen
- 9 Overall sheen
- 10 " "
- 11 sheen w/ riser.
- 12 elevation line bright against the building
- 13 little pond w/ pump. manual pump.
- 14 pump. again
- 15 Directly behind lubricants drum.
- 16 batteries
- 17 another view of drums, showing oil stain

- 18 Close up view of open bucket in 15 balancing in the back
- 19 Trenched to little pond
- 20 leaking ground kitty litter
- 21 Close up the leaking, along the wall, see kitty litter ^{oil dry.}
- 22 close up of 2 tanks in the building, crusher motor, leaking
- 23 hydraulics with oil underneath
- 24 looking at debris metal separator, water is trenched little pond
- 25 Close up of debris, see oil.
- 26 another view of oil pooling towards trench-
- 27 over all site view from stairs.
- 28 Over all view ↗
- 29 entrance to trench.
- 30 trench going into pond - already ^{other side}
- 31 opposite side of wall from #30 root of scrap bay.
- 32 close up of manual pump
- 33 other side heavy staining
- 34 view copper scrap sitting in pools of liquid

- 34 debris adjacent to big pond
- 35 red hose from the pond
- 36 view to the right of pond
- 37 another view debris
- 38 ladder next to pond, entrance of pond.
- 39 oil absorbant pig, entrance to the pond
- 40 view of sock in relation to pond.
- 41 turn around overall facility view
- 42 orange original color of absorbant sock
- 43 Close up view of the sock
- 44 Close up view of Drum next to entrance of pond
Uncovered, gray fluid.
- 45 leaking oil, while walking under ~~the~~ belt of crusher
- 46 walk out of entrance, path of fluids on the ground.
- 47 overall view, drums, waste oil, oil filters in a drum.
- 48 air conditioning units w/ foam,
- 49 close up of leak from those units
- 50 view of perimeter toward entrance.
- 51 looking opposite direct

52 everything draining, opposite side of entrance, flow of water.
DC property adjacent to site, cement mixer

53 Diesel 500 gal @ gate. oxygen tank.

trickle of leak, next to vehicle entrance, concrete crowd.

54 White cylinders, tank of fuel used for torches,

55 turned around, weigh station, magnet separator.

Note pooling water.

56 Coming out under the fence, onto DC property.

57 Propane tanks - maybe for scrap.

58 materials stored on DC property, ~~two~~ dumpsters Concrete mixer
Note water pooling

59 Additional staining on outside on DC strain

60 - same photo - know its not a shadow

61 sediment tracking

62 sediment tracking

63 additional view of tracking

64 metal Dumpster, super salvage

65 + pooled water.

66 Box with oil staining on outside

67 engine part in the box, variety of parts, inside view

68 Oil sheen, underneath tanks near entrance.

69 Additional view, close up.

70 another view of tank, sitting on top of second containment

71 oil filters in a drum overflow w/ bucket full of oil.

72 tote of plastic, not designed to contain oil, waste oil.

73 from outside of the fence, oil staining

74 view from outside the fence, note staining

75 two barrels w/ oil filters, sitting on top of 2nd containment
on top of berm.

76 outside at Gate, patties, staining

77 tanks for cutting torches by the gate

78 staining w/ Dumpsters outside the fence.

79 stained dumpsters

80 path of sediment towards storm drain

81 storm drain with a discharge

82 stuff entering the storm drain at the intersection

83 picture of street sign.

84 gutter/ roof drain near oil stained exterior

85 staining with oil dry next to storm drain